

## Oil-In-Water Mascara - "Gold Shine"

## Color Cosmetics

Ref: CC/0028/EU

Product Name	INCI Name	%W/W	Supplier
<b>A</b>			
		100.00	
Water	Aqua	56.25	
Keltrol T	Xanthan Gum	0.15	www.cpkelco.com
Veegum HV	Magnesium Aluminium Silicate	0.55	www.rtvanderbilt.com
MBD 201 20% Dispersion	Carbon Black (and) Aqua	5.00	www.geotech.nl
<b>B</b>			
EDTA BD	Disodium EDTA	0.05	www.basf.com
Methyl-4-hydroxybenzoate H 5501	Methylparaben	0.30	www.sigmaaldrich.com
Triethanolamine	Triethanolamine	0.50	www.vwr.com
1,2-Propandiol	Propylene Glycol	2.00	www.vwr.com
<b>C</b>			
Prestige® Sparkling Pure Gold	Mica (and) Titanium Dioxide (and) Iron Oxides	3.00	www.eckart.net
<b>D</b>			
Dow Corning 245 Fluid	Cyclopentasiloxane	5.00	www.dowcorning.com
Dow Corning 5225C Formulation Aid	Cyclopentasiloxane and PEG/PPG-18/18 Dimethicone	1.00	www.dowcorning.com
Ewacera 12	Bees Wax	10.00	www.wagnerlanolin.de
Kortacid 1895	Stearic Acid	2.00	www.akzonobel.com
Imwitor 960K	Glyceryl Stearate	2.00	www.sasolwax.com
Lanette 18	Stearyl Alcohol	2.00	www.cognis.com
Permethil 104A	Polyisobutene C68	1.00	www.cheshamchemicals.com
Phenonip	Phenoxyethanol (and) Methylparaben (and) Butylparaben (and) Ethylparaben (and) Propylparaben (and) Isobutylparaben	1.20	www.clariant.com
Luviskol K30 Powder	PVP/ Polyvinylpyrrolidone	4.00	www.basf.com
Ewacera 34	Carnauba Wax	4.00	www.wagnerlanolin.de

### Procedure

1. Mix phase A.
2. Mix phase B and add to phase A
3. Add phase C to phase AB and heat up to 75°C
4. Mix phase D and heat up to 75°C
5. Add phase D to phase ABC
6. Cool down while stirring and pour into an appropriate container

### Stability

Stable for at least 3 months at RT and 40°C.

### Customer Support

ECKART GmbH & Co. KG  
info.eckart@altanachemie.com

ECKART Cosmetic Colours LLC  
info.eckart.usap@altanachemie.com

ECKART Asia Limited  
info.eckart.asia@altanachemie.com

This information and our technical advice - whether verbal, in writing or by way of trials - are given in good faith but without warranty, and this also applies where proprietary rights of third parties are involved. Our advice does not release you from the obligation to verify the information currently provided - especially that contained in our safety data and technical information sheets - and to test our products as to their suitability for the intended processes and uses. The application, use and processing of our products and the products manufactured by you on the basis of our technical advice are beyond our control and, therefore, entirely your own responsibility.